maintainance work

1:- 10 - 14.

Date	SL.NO	Motar-HP	Materials
4-10-14 8/10/14	01.	10/20.	Motar Windieng. N.R.V. unina elbu
06/10/14 11/10/14,	02.	10/20.	Motar winding. Motar Bush. Bering PUMP Emplears. 10pcs. Gaid with 10 pcs Bus, Slve.
07/10/14 12/10/14.	03.	10/20.	Motar Windeing. Motar Bush. Bereing mater sofatu
07/10/4 12/10/14	04.	12/25	Motar Wiedeing Bush Bereing.
10/10/14 14/10/14	05	7½/10	Motar Wieding Bush Bereing. PUMP. Bush Sleve.
12/10/14 15/10/14.	06	15/30.	Motar Wiending.

W:6 DATE: PAGE: 61

	Place	
30	Sharadi Sai Ratan layout II^ed Time. BR	
25	Thanisandra Kempamma House. Near. BR	
30.	Rachenna halli Masana. BR	
30.	Rachenahalli Lake, II^ed Time. BR	
6	Dasarahalli School Campoud.	
40	Mareyamma Pulya.	

1/9/2015

Date	SL.NO	motor HP	materials
12/9/15 14/9/15 ~~14/9/15~~	8	10 H.P	Motor winding Motor Bush. Baring set
18/9/15 20/9/15 ~~20/9/15~~	9	15 HP	Motor winding, motor Bush test Baring set starter — pewender, relay, contact blades pump — Bush, sleeve, 10 Impller
18/9/15 20/9/15	10	10 HP.	motor winding, motor soft, motor Bush. Test baring set starter — pewender relay
18/9/15 22/9/15	11	15 HP	motor winding, motor Bush.
18/9/15 25/9/15	12	15 HP	motor winding, Test baring set, Bush.

DATE: PAGE: 29

Pipe	Place	Sign
20	shabari Nagara 3rd cross.	
27	Hegde Nagara (New Shanthi nagara)	
25	Dasarahalli chowdeswari devasthana.	
45	Thamisandra. (KEB Narayanaswamy ~~to~~ near house).	
45	Rachenahalli (over tank)	

25/9/15

Assistant Executive Engineer
Byatarayanapura Sub Division

1/10/2015

Date	Sl.No	H.P	Materials.
1/10/15	1	12.5 HP	pipe had a holes.

DATE: PAGE: 30

Pipe	place	Signature
30	Akashavani layout Basavahalli (BN 6th cross)	

31/12/2015
Assistant Executive Engineer
Byatarayanapura Sub Division
B.B.M.P. Bangalore

5/10/15
ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ